Low risk

No further action required. Supplier is approved, orders can be placed.

Medium risk

By defining and implementing suitable corrective measures, the supplier can be granted restricted approval. The supplier can therefore be awarded contracts, but must fulfill all agreed measures by the agreed target date.

High risk

The supplier does not meet Rommelag's requirements. The supplier is blocked, orders cannot be placed.

reservation

remedial measures

Review of the

implementation